


Keel Display Installation Diagram



Diverse Yacht Systems specification software version 1.0 Setup Procedure:

1. Calibration Mode is entered by pressing push-button during 'Splash Screen' display within first 10 seconds after power up.
2. Display shows 'CAL PORT'. Set keel to maximum travel to port and press push-button.
3. Display shows 'CAL MID'. Set keel to centre and press push-button.
4. Display shows 'CAL STBD'. Set keel to maximum travel to starboard and press push-button.
5. Display shows 'CAL DONE' for 2 seconds and resumes normal operation.